



Figure 10 The four arrows in the diagram above show the forces that must act on a shear wall for it to work as intended. Shear panels nailed to the wall framing transfer forces from the top to the bottom and from one side of the wall to the other. These forces are transferred in line with each particular framing member. Because of this, the sill cannot transfer enough vertical force into the shear wall to resist overturning.